



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2335

Work Order Type: Weatherization

Audit Name: 14014SO2335

CLIENT INFORMATION

Client Name:

Address:

Client ID: 14014SO2335

FAYETTEVILLE, TN 37334

Alt. Client ID: LINCOLN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY

Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY

Fax: (931) 438-0074

FAYETTEVILLE, TN 37334-2001

Email Address: e.satterfield@schra.us

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: 14014SO2335

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2335

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0

Page 1 of 4

Measures

Measure 1 General Air Sealing

Components

Inspected

- Comment** 1. SEAL DUCT WORK - REGISTERS TO READ 1.0 OR LESS / USE MASTIC AT REGISTERS AND RETURN
2. REPLACE INSULATION AFTER DUCT SEALING / INSTALL ACCESS DOOR FOR FOUNDATION / INSTALL PLYWOOD (1/2") AND SEAL WALL BEHIND UNIT
3. W/S AND D/S FRONT DOOR
4. COOL SEAL ROOF
5. WRAP FIRST 5FT OF HOT AND COLD

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Supplies	Infiltration Reduction	Each	1					
2	Labor	LABOR	Hour						
Other Detail									
Measure Sub Total:							Sub Total:		

Field Notes:

Measure 2 Fix Improper Venting (Clothes Dryer)

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Metal Flex	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>

Field Notes:

Client Name:

Client ID: 14014SO2335

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2335

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0

Page 2 of 4

Measure 3 Install Kitchen Exhaust Fan**Components****Inspected****Comment** REPLACE DAMPER AT STOVE HOOD AND INSTALL NEW STOVE HOOD☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Kitchen exhaust fan (Range Hood)	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 4 Smoke Detector is Needed****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke / Carbon detector	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 14014SO2335

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2335

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 4

**Measure 5 Vapor Barrier Needed
(Basement/Crawlspace)****Components****Inspected****Comment**

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Basement / crawlspace vapor barrier	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 14014SO2335

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2335

Report Run On: 5/28/2010

DOE Weatherization Assistant

Version 8.5.0

Page 4 of 4